



Termination of support for Auto-Shot Sampler with ball-valve mechanism	
Category	<input type="checkbox"/> New product <input type="checkbox"/> Spec revision <input type="checkbox"/> Price revision <input type="checkbox"/> Discontinued <input checked="" type="checkbox"/> Others (Support term)
Products affected	Auto-Shot Sampler (model: AS-1020E)
<p><Overview></p> <p>Two types of mechanism, i.e., ball-valve and gate valve mechanisms exist for Auto-Shot Sampler. The support for the Auto-Shot Sampler with the ball-valve mechanism will be terminated on December 31, 2014. When the support term ends, no repair service will be provided.</p> <p>We would recommend that those customers who use Auto-Shot Sampler with the ball-valve mechanism consider purchasing the Auto-Shot Sampler with the gate-valve mechanism.</p> <p><Distinguishing ball-valve and gate-valve mechanisms></p> <p>The two types of Auto-Shot Samplers are shown in Fig. 1 and Fig. 2.</p> <p>Serial numbers of Auto-Shot Samplers with the ball-valve mechanism have last three digits of 157 or less. Examples are:</p> <p>ASxxxx101: Ball-valve ASxxxx201: Gate-valve</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>Front view (housing cover removed) Fig. 1 Ball-valve mechanism</p> </div> <div style="text-align: center;">  <p>Front view (housing cover removed) Fig. 2 Gate-valve mechanism</p> </div> </div> <p><Reason for support termination></p> <p>Since it has been more than ten years since Auto-Shot Sampler with the ball-valve mechanism was discontinued, it is extremely difficult to obtain parts for repair.</p>	
Contact	Frontier Laboratories Ltd. (www.frontier-lab.com) 1-8-14 Saikon, Koriyama, Fukushima 963-8862 Japan Phone: +81-024-935-5100 FAX: +81-024-935-5102 Email: cs@frontier-lab.com